




2.- POR OTRO LADO, SE PRETENDE LA REFORMA DE LA ZONA DE PISTAS PARA NIVELARLAS Y EVITAR LA MULTITUD DE DESNIVELES Y ESCALONES QUE PRESENTAN EN LA ACTUALIDAD. ASÍ COMO REPARAR EL ESTADO DETERIORADO QUE PRESENTAN LAS MISMAS. LA INTERVENCIÓN SE CENTRARÁ ÚNICAMENTE EN LA MITAD DE LAS PISTAS, CORRESPONDIENDO CON LAS QUE ESTÁN EN PEOR ESTADO.

A map of the San Antonio de Velilla area. The map shows a network of roads, including M-208 and Ruta 66. Key locations marked include 'Restaurante Quinta San Antonio de Velilla' (orange icon), 'Ahorramas' (blue icon), 'Velilla de San Antonio' (yellow label), 'Colegio Público Valdemera' (red pin), 'Lagunas de Velilla' (green icon), and 'Parque Infantil Gigantes' (green label). A blue river or canal flows through the bottom left of the map.

 Dirección General
de Infraestructuras y Servicios
VICEPRESIDENCIA, CONSEJERÍA DE EDUCACIÓN Y
UNIVERSIDADES

PROYECTO BÁSICO Y DE EJECUCIÓN DE SUSTITUCIÓN
DE CUBIERTAS Y ADECUACIÓN DE PISTAS DEPORTIVAS
EN EL CEIP VALDEMERA

A rectangular circuit diagram. On the right side, there is a battery symbol consisting of two parallel vertical lines of unequal length. A wire extends from the top of the battery to the left, where it connects to a light bulb symbol (a circle with a cross inside). The wire continues to the left and then turns downwards to complete the circuit back to the bottom of the battery.

01U01

ESCALA
DINA2 1/400
FECHA mayo 2023

4 REAL_OFICINA TÉCNICA ARQUITECTURA E INGENIERÍA